

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2023

Submitted Date:

10/11/2023

Document Number:

712700729

**FIELD INSPECTION FORM**

Loc ID 320863 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 22 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 600 17TH STREET STE 1400S  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Hanson, Mike	(505) 330-2903	mhanson@catamountep.com	<a href="#">All SW Inspections</a>
, Engineering		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205261	WELL	PR	03/01/2020	CBM	007-06140	PARGIN MOUNTAIN UNIT 11	PR
456218	WELL	PR	12/20/2019	CBM	007-06330	EBC 9	PR
456219	WELL	PR	12/24/2019	CBM	007-06331	EBC 10	PR

**General Comment:**

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Locked combo gate from Fosset Gulch road.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placards on produced water tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal signs posted at location entrance.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning signs on pumpjacks.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Contents labels on chemical additives and lube oil containers.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 emergency number posted on wellhead signs.		
Corrective Action:		Date:	_____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Location has received a ground treatment to retard vegetation.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Pipe rail		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Vertical Heated Separator	# 1		corrective date
Comment:	_____		

Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Telemetry, 2 electric boxes with solar panel, portable toilet, produced water transfer house.		
Corrective Action:		Date:	
Type: Prime Mover	# 3		
Comment:	Natural gas motor.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:	3 on separator vent stack, 2 on tank heater vent stacks.		
Corrective Action:		Date:	
Type:	#		
Comment:	2" line from Pargin Mountain wellhead to separator, 2 4" and 2 2" lines from #9 and #10 wellheads to separators, 3 lines from separators to produced water tanks, 2 2" lines from separators to #9 and #10 gas powered prime movers.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Pump Jack	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Accessible		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Chemical additive container at the #10 separator.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Calibration date 9/25/2023.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		37.146700,-107.382080
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Plastic barriers with liner material.			
Corrective Action:				Date:

<b>Wells Served By Facilities Above</b>		<b>AirsID</b>	
API Number	API Number	AirsID	
007-06331			
007-06330			

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 205261 Type: WELL API Number: 007-06140 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/16/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456218 Type: WELL API Number: 007-06330 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/21/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 51 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456219 Type: WELL API Number: 007-06331 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/21/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Rip Rap	Pass					
Berms	Pass	Ditches	Pass			
Compaction	Pass					
Gravel	Pass					
Ditches	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700732	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280759">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280759</a>