

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2023

Submitted Date:

10/11/2023

Document Number:

712700731

**FIELD INSPECTION FORM**Loc ID 320856 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 600 17TH STREET STE 1400S

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	All SW Inspections
, Engineering		dnr_cogccengineering@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205244	WELL	PR	01/01/2020	CBM	007-06122	BULL CREEK FEDERAL A 1	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Access through FS gate from Fosset Gulch road.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Warning signs posted on location.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Metal sign posted at location entrance.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	24 operator contact number and 911 emergency number posted on well location signage.			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Angle iron			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Ancillary equipment	# 1			
Comment:	Wellhead			
Corrective Action:				Date:
Type: Flow Line	# 3			
Comment:	2" line from wellhead to separator, 2" line from separator to gas powered prime mover, line from separator to produced water off location.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Natural gas motor.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On separator vent stack.			
Corrective Action:				Date:

Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration date 6/27/2023.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Lube oil container.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 205244 Type: WELL API Number: 007-06122 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test:  Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure:  Fluid Type: End Surf Csg Pressure: Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Ditches	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Waddles	Pass					
Ditches	Pass	Culverts	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700734	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280761">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280761</a>