

Final Reclamation Inspection

September 28th, 2023

Operator: Enduring LLC - 10663

Location ID: 326325

Inspection Document #: 714000030

La Plata County, CO

Township: SWSE 8 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 1. Overview photo of the disturbance taken from the access road entry point facing north.



Inspection Photos

Location Name: Animas Wheeler 8-1

Location ID: 326325



Photo 2. Photo of gully erosion observed on the fill slope, located on the eastern edge of the disturbance.

Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 3. Rill erosion observed in several locations along the fill slope located on the eastern edge of the disturbance.

Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 4. Silt fence along eastern edge of disturbance is in disrepair and is no longer functioning. BMP's used to minimize erosion and degradation of the location are inadequate.

Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 5. Eastern portion of disturbance is largely composed of annual, weedy vegetation including cheatgrass and kochia.



Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 6. Kochia observed in various locations throughout the active disturbance.

Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 7. Western portion of the disturbance meets 80% vegetation threshold standards and appears reflective of reference areas.

Inspection Photos
Location Name: Animas Wheeler 8-1
Location ID: 326325



Photo 8. Reference area comprised of Juniper, antelope bitterbrush and indian rice grass.