

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2023

Submitted Date:

10/11/2023

Document Number:

690011470

FIELD INSPECTION FORMLoc ID 452820 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453000	WELL	PR	10/05/2018	OW	123-45858	HERGENREDER 25N-4HZ	PR
453001	WELL	PR	05/01/2023	OW	123-45859	HERGENREDER 7N-4HZ	PR
453002	WELL	PR	10/03/2018	OW	123-45860	HERGENREDER 5N-4HZ	PR
453003	WELL	PR	01/01/2020	OW	123-45861	HERGENREDER 32N-4HZ	PR
453004	WELL	PR	04/01/2023	OW	123-45862	HERGENREDER 22N2-4HZ	PR
453005	WELL	PR	06/01/2023	OW	123-45863	HERGENREDER 6N-4HZ	PR
453006	WELL	PR	02/01/2021	OW	123-45864	HERGENREDER 22N1-4HZ	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 7		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Battery location number: 464139				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 453000 Type: WELL API Number: 123-45858 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/25/2022

Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Plumbed to surface.

Corrective Action:

Date:

Facility ID: 453001 Type: WELL API Number: 123-45859 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/06/2023

Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 68 Fluid Type: GASEnd Surf Csg Pressure: 1Comment: Plumbed to surface.

Corrective Action:

Date:

Facility ID: 453002 Type: WELL API Number: 123-45860 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/25/2022

Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Plumbed to surface.

Corrective Action:

Date:

Facility ID: 453003 Type: WELL API Number: 123-45861 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/02/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____

Date: _____

Facility ID: 453004 Type: WELL API Number: 123-45862 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 03/07/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 49 Fluid Type: GAS

End Surf Csg Pressure: 1

Comment: Plumbed to surface.

Corrective Action: _____

Date: _____

Facility ID: 453005 Type: WELL API Number: 123-45863 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 05/25/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action: _____

Date: _____

Facility ID: 453006 Type: WELL API Number: 123-45864 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 05/25/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action: _____

Date: _____

COGCC Comments		
Comment	User	Date
Routine wellhead inspection.	carlilec	10/11/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690011471	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281232