

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2023

Submitted Date:

10/11/2023

Document Number:

705000469

FIELD INSPECTION FORM

Loc ID 328854 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248717	WELL	SI	02/01/2021	GW	123-16519	HSR-HOUSE 6-20	PA
328854	LOCATION	AC			-	HSR-HOUSE-63N65W 20SENW	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 248717 Type: WELL API Number: 123-16519 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (HSR House 6-20); ECMC form 42 notice of start of plugging operations doc #403440357 received on 06/21/2023. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location flowlines have been removed; wellhead, dump and process flowlines at facility/ battery are removed. No flowlines/ risers observed on location. Fenced excavations observed on location at PA well, flowline and facility/ battery areas. Excavation/ remediation work is in progress.

Corrective Action: _____ Date: _____

Facility ID: 328854 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403551889 received on 10/06/2023: While conducting flowline removal activities associated with the House 6-20 wellhead, historically impacted soil was discovered at the separator riser. The volume of the release is unknown. Assessment activities are ongoing. The flowline and associated wellhead are being permanently removed.	maclarej	10/11/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000471	Fenced excavation at PA well; view N to battery area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281620
705000472	Fenced excavation at facility area; FL removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281622