

Inspection Photos

Loc: 324494

Operator: **OXY USA INC**

Inspection Date: 10/11/2023

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the access road. There is erosion occurring across the road and no BMP's were installed. The access road will need to be decompacted and reclaimed. Previous corrective action has not been completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 10/11/2023

Inspection Photos



Photo 2. Facing south toward the location. The well has been plugged and abandoned . The location will need to be recontoured back to the original contours and reclaimed. This gate does not prevent livestock entry..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 10/11/2023

Inspection Photos



Photo 3. Facing toward the wellsite. The wellhead has been covered up and backfilled. This pipe riser must be removed. All equipment must be removed with 3 months of abandonment.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 10/11/2023

Inspection Photos



Photo 4. Facing south toward the fill slope which must be recontoured back to the original condition.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324494 | Date: 10/11/2023

Inspection Photos



Photo 4. Facing northeast at the location. There are noxious weeds that remains hat have seed heads that must be bagged and removed. Red arrow points to Diffuse knapweed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 10/11/2023