

# Interim Reclamation and Stormwater Inspection

Date: 10/05/2023

Operator: TIMKA RESOURCES LTD - 88370

Location ID: 322914

Inspection Document #: 708200605

Weld County, CO

SESE Section 35 T8N R57W

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



**Photo 1.** This location does not comply with Rule 1002.f. During this inspection, Staff observed rill erosion degradation occurring along the access road; originating near the produced water tank and traveling south along the access road towards HWY 14. Implementation of additional stormwater controls measures/BMPs and/or maintenance is required.

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



**Photo 2.** See comments in Photo 1.

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



**Photo 3.** See comments in Photo 1.

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



10/5/23, 1:12 PM  
180° S  
ECMC

**Photo 4.** See comments in Photo 1. Russian thistle also observed (red circle)

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



**Photo 5.** See comments in Photo 1.

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



**Photo 6.** See comments in Photo 1. Colorado List C Noxious Weed- Field Bindweed- observed to be growing throughout the access road (example in red circle).

Inspection Photos  
Location Name: Bounty 1  
Location ID: 322914



**Photo 7.** Russian thistle observed to be growing near the produced water tank and tank battery.