

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2023

Submitted Date:

10/12/2023

Document Number:

708200605

FIELD INSPECTION FORM

Loc ID 322914 Inspector Name: Edwardson, Dylan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 88370
Name of Operator: TIMKA RESOURCES LTD
Address: 2077 BAYFRONT DR
City: WINDSOR State: CO Zip: 80550

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|----------------------------|-----------|
| PIVONKA, TIMOTHY | 970-667-9861 | timkaresources@hotmail.com | PRESIDENT |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|----------------------|-------------|
| 244463 | WELL | PR | 06/01/2001 | OW | 123-12258 | BOUNTY 1 | RI |
| 322914 | LOCATION | AC | | | - | BOUNTY-68N57W 35SESE | RI |

General Comment:

This is an Interim Reclamation and Stormwater Inspection for Location ID (322914).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Colorado List C Noxious Weed (Field Bindweed) was observed to be growing along the access road and Russian Thistle was observed near the tank battery. Both require management/eradication.

Corrective Action: Comply with Rule 606. Location will remain out of compliance until the corrective action has been resolved.

Date: 10/05/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 244463 Type: WELL API Number: 123-12258 Status: PR Insp. Status: RI

Facility ID: 322914 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: This location does not comply with Rule 1002.f. During this inspection, Staff observed rill erosion degradation occurring along the access road; originating near the produced water tank and traveling south along the access road towards HWY 14. Implementation of additional stormwater controls measures/BMPs and/or maintenance is required. Refer to attached inspection photos.

Corrective Action: Comply with Rule 1002.f. The location will remain out of compliance until the corrective action has been resolved.

Date: 10/05/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 708200610 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6283274 |