

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/06/2023

Document Number:

712700708

**FIELD INSPECTION FORM**Loc ID 333541 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10684

Name of Operator: EPIC ENERGY LLC

Address: 332 RD 3100

City: AZTEC State: NM Zip: 87410

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Arleen		arleen@walsheng.net	SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Thompson, Paul		paul@walsheng.net	Principal Agent
Martinez, Shawna		shawna@walsheng.net	SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214097	WELL	PR	07/01/2023	GW	067-05404	BONDAD 33-9 34	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Access from County Road 310.				
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Contents and volume labeling, NFPA placards on produced water tanks.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Metal sign posted on produced water tank fencing.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	24 hour operator contact number is functional, well location signage missing local emergency services number.				
Corrective Action:	Post local emergency services number or 911 on well location signage.				Date: 11/06/2023
<b>Good Housekeeping:</b>					
Type	OTHER				
Comment:	Location is bisected by pipeline ROWs and access roads to two adjacent well locations.				
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	TANK BATTERY				
Comment:	T-post, pipe rail and hog wire around produced water tanks.				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Bradenhead	# 1				
Comment:	Not accessible				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Wellhead				
Corrective Action:					Date:
Type: Deadman # & Marked	# 1				
Comment:	One unmarked guy anchor.				

Corrective Action:	Mark or remove if not serviceable or not needed for ongoing operations.		Date:	10/20/2023
Type: Bird Protectors	# 2			
Comment:	On separator vent stack.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	2" line from separator to meterhouse. Telemetry on meterhouse. Calibration date 9/11/2023.			
Corrective Action:			Date:	
Type: Flow Line	# 2			
Comment:	2" line from wellhead to separator. 2" line from separator to separator.			
Corrective Action:			Date:	
Type: Gathering Line	# 1			
Comment:	Above ground dogleg valve.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.100520,-107.792760
Comment:	Screened, open top steel tank, 94 bbls.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	Open Top		37.100400,-107.792890
Comment:	Screened, open top steel tank, 118 bbls.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 214097 Type: WELL API Number: 067-05404 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/15/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Ditches	Pass	Ditches	Pass			

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403552829	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276395">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276395</a>
712700714	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276375">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276375</a>