

# Inspection Photos

10/09/2023

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 335455

**Inspection Doc:** 696205336

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 1:** Photos 1-2 taken from west end of the working pad surface. Photos provide an overview of the pad from north, northeast, southeast to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 3:** Photos taken from the interim areas on the west end of the Location. Photos show reclamation, including recontouring/regrading and revegetation work has been performed on areas not needed for production.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 4:** Photos show the two sediment traps constructed along the western working pad surface.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 5:** Photo taken from the sediment trap on the western working pad surface. Photo example showing inlet/outlet armoring has not been constructed in conjunction with geotextile lining per good engineering practices.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 6:** Photo taken from the northwestern end of the working pad, facing south. Photo example showing a diversion ditch leading from the sediment trap. Ditch has been lined with erosion blankets in conjunction with rock checks to mitigate stormwater velocity.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 7:** Photo shows unused flagpole stored next to the tank battery, on the north end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 8:** Tank battery facility, north end of the Location. Tank battery signage not posted pursuant to Rule 605.e



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 9:** Photo taken from the tank battery facility. Capacity labeling on tank no longer legible.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335455



**Photo 10:** Photo taken from the southwest end of the working pad. Photo shows unmarked anchor.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources