

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE SR 12-9 Pad

Location # 335043



Oct 12, 2023 at 1:32:56 PM
CO

Photo # 2693 From entrance to location



Oct 12, 2023 at 1:33:00 PM
CO

Photo # 2694 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE SR 12-9 Pad

Location # 335043



Photo # 2695 Location



Photo # 2696 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE SR 12-9 Pad

Location # 335043



Photo # 2697 Location



Photo # 2698 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE SR 12-9 Pad

Location # 335043



Photo # 2699 Location



Photo # 2700 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE SR 12-9 Pad

Location # 335043



Photo # 2701 SR 411-9 rupture disk vent line lacks cap



Photo # 2702 SR 411-9 rupture disk vent line lacks cap

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE SR 12-9 Pad

Location # 335043



Photo # 2703 Open ended load line