

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/07/2023

Document Number:

708901885**FIELD INSPECTION FORM**
 Loc ID 334619 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264718	WELL	PR	03/01/2019	GW	045-08937	DUMAS 14-16A(P14)	PR
264719	WELL	PR	05/15/2003	GW	045-08941	COUEY 23-1 (P14)	PR
264720	WELL	PR	05/06/2003	GW	045-08940	RANCH 14-10D (P14)	PR
264721	WELL	PR	10/09/2008	GW	045-08939	ROE 13-13B (P14)	PR
264722	WELL	PR	03/01/2023	GW	045-08938	DUMAS 14-16D (P14)	PR
266559	WELL	SI	04/01/2023	GW	045-09151	ROE 13-12D (P14)	SI

General Comment:**CECMC Inspection Report Summary**

On 10/05/2023 at approximately 10:09 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at CAERUS PICEANCE LLC DUMAS P14 Pad.

Location # 334619 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear/NSO Habitat areas.

Location is approximately 42 yards from West Mamm Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Rupture disc vent line lacks cap with a CA date of 10/14/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [911/970-285-2615](tel:9119702852615)

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rupture disc vent line lacks cap		
Corrective Action:	Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.		Date: 10/14/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Unlined containment			
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected FacilitiesFacility ID: 264718 Type: WELL API Number: 045-08937 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 264719 Type: WELL API Number: 045-08941 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 264720 Type: WELL API Number: 045-08940 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 264721 Type: WELL API Number: 045-08939 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 264722 Type: WELL API Number: 045-08938 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 266559 Type: WELL API Number: 045-09151 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In☐ Temporarily Abandoned

Reminder: _____

Comment: PA

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse in areas
Berms						
		Ditches				
		Gravel				Sparse in areas
Compaction						Light compaction in areas
Ditches						
		Culverts				
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	10/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403553362	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6277112
708901886	Inspection 708901885 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6277110
708901887	Inspection 708901885 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6277111