

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 163 yards from Spruce Creek.

Section/Township/Range: 34 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Photo # 2421 Rip Rap/BMP needs maintenance



Photo # 2422 Rip Rap/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Photo # 2423 Rip Rap/BMP needs maintenance



Photo # 2424 Rip Rap/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Photo # 2425 Rip Rap/BMP needs maintenance



Photo # 2426 Rip Rap/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Photo # 2427 Erosion & transport of sediment on lease road near entrance to location



Photo # 2428 Erosion & transport of sediment on lease road near entrance to location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Photo # 2429 Culvert on lease road needs maintenance



Photo # 2430 Culvert on lease road needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOAD RMV 73-34 Pad
Location ID: 324007



Photo # 2431 Culvert on lease road needs maintenance

Photo # 2432 Culvert on lease road needs maintenance