

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 40.077800 Long: -104.893300

Wind: Calm Speed: 2 (mph) Direction From: W Weather: Clear Temperature: 71 (F)

Assisting Staff: Brittani Santistevan Camera #: _____

Visible Smoke Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1:45	PM	2:00	PM	

Comment: Surveyed field north of the pumpjack. Land owner stated to be a "dead spot" in his field. It appears that according to our flowline map, a flowline runs near the spot that was surveyed with a FLIR camera.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>No evidence of a leak at location that was surveyed with the FLIR camera. Vegetation appears to not be growing in area north of pumpjack. See attached video footage and photos.</u>	santistb	10/16/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714200185	FLIR Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286214
714200186	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286215