

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/10/2023

Document Number:

699107542**FIELD INSPECTION FORM**Loc ID 331757 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 65110Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH State: NH Zip: 03801**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------------|-----------------------|---------------------------------|
| Forma, Joseph | 603-427-2099 x111 | joeforma@obenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|------------------------------------|-------------|
| 331757 | LOCATION | AC | | | - | NORTH LOST CREEK- 63N62W 20SWNE | SI |

General Comment:[Tank Battery Inspection.](#)[This is a follow up to prior inspection document number #699107162. CA's were not corrected.](#)

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|------------|
| Type | BATTERY | | |
| Comment: | Missing Battery sign. See attached photos | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | Date: | 09/22/2023 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Missing pit capacity label. See attached photo | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 09/22/2023 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Missing NFPA placard for the pit. See attached photo | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 09/22/2023 |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Overgrown vegetation around the tank battery needs to be removed for good housekeeping. See attached photos | | |
| Corrective Action: | Comply with Rule 606 | Date: | 09/22/2023 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------|---|-------|-----------------|
| Type: Other | # | | corrective date |
| Comment: | Unmarked risers need marked. See attached photo | | |
| Corrective Action: | Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b | Date: | 09/22/2023 |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 331757 Type: LOCATION API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI Tank Battery
No FIRR was submitted.

Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.

Date: 10/12/2023

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 0907hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107162 at North Lost Creek-63N62W 20SWNE Tank Battery of O'Brien Energy Resources Corp. Location ID #331757 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Missing pit capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Missing NFPA placard for the pit. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Missing Battery sign. Install sign to comply with Rule 605.a. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation around the tank battery needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>Unmarked risers need marked. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. With a Corrective Action date of 9/22/23</p> <p>No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/12/23</p> <p>No CA's were corrected</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p> | burnsa | 10/10/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403556087 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279736 |
| 699107543 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279696 |