

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2023

Submitted Date:

10/16/2023

Document Number:

713300208

FIELD INSPECTION FORM

Loc ID 336390 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|----------------------------------|---------------------------------|
| | | Cogcc.inspections@crestonepr.com | ALL INSPECTIONS |
| Silver, Randy | | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 206562 | WELL | SI | 06/01/2022 | GW | 013-06057 | ALCORN 1 | SI |
| 294745 | WELL | SI | 06/01/2022 | GW | 013-06579 | ALCORN 32-10 | SI |

General Comment:

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | metal panels | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-----------------------------------|-----------------------|-------|-----------------|
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | cailbration card 9-23 | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |

| | |
|-------------------------------|-------|
| Comment: | |
| Corrective Action: | Date: |
| Type: Ancillary equipment # 1 | |
| Comment: automation panel | |
| Corrective Action: | Date: |
| Type: Bird Protectors # 2 | |
| Comment: | |
| Corrective Action: | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 150 Bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | shared with condensate tank | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Wells Served By Facilities Above

API Number

013-06057

013-06579

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 206562 Type: WELL API Number: 013-06057 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: at time of inspection valves appeared to be closed

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 11/22/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 237 Fluid Type: GAS

End Surf Csg Pressure: 85

Comment:

Corrective Action: Date:

Facility ID: 294745 Type: WELL API Number: 013-06579 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: at time of inspection valves appeared to be closed

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 11/22/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 100 Fluid Type: GAS

End Surf Csg Pressure: 45

Comment:

Corrective Action: Date:

COGCC Comments

| Comment | User | Date |
|------------------------------------|---------|------------|
| Routine inspection | kesterm | 10/16/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713300209 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286344 |