

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 1: Wellhead Sign



Photo 2: Pumpjack

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 3: Wellhead Sign



Photo 4: Wellhead



Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Energy & Carbon Management Commission
40.13907, -104.69499, 1477.4m, 325°
Oct 17, 2023 11:37:14

Photo 5: Wellhead Sign



Energy & Carbon Management Commission
40.13907, -104.6949, 1494.5m, 314°
Oct 17, 2023 11:37:24

Photo 6: Wellhead

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 7: Wellhead Sign



Photo 8: Wellhead

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 9: Wellhead Sign



Photo 10: Wellhead



Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 11: Wellhead Sign



Photo 12: Wellhead

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 13: Wellhead Sign



Photo 14: Wellhead

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 15: Tank Battery



Photo 16: Equipment

Inspection Photos
Location Name: Melbon 12C-8HZ
Location ID: 431712



Photo 17: Gas meter disconnected




Photo 18: Gas meter disconnected