

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



**Location Overview: Location is within High Priority/Density
Habitat areas. Location is approximately 22 yards from a
drainage that contributes to the Colorado River.**

Section/Township/Range: 20 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



Photo # 2884 Sediment migrating onto gravel track pad/BMP needs maintenance



Photo # 2885 Sediment migrating onto gravel track pad/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



Photo # 2886 Sediment migrating onto gravel track pad/BMP needs maintenance



Photo # 2887 Sediment migrating onto gravel track pad/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



Photo # 2888 Sediment migrating onto gravel track pad/BMP needs maintenance

Photo # 2889 Sediment migrating onto gravel track pad/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



Photo # 2890 Sediment migrating onto gravel track pad/BMP needs maintenance



Photo # 2891 Sediment migrating onto gravel track pad/BMP needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



Photo # 2892 Sediment migrating onto gravel track pad/BMP needs maintenance