

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2023

Submitted Date:

10/11/2023

Document Number:

712700729**FIELD INSPECTION FORM**Loc ID 320863 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 600 17TH STREET STE 1400SCity: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Hanson, Mike	(505) 330-2903	mhanson@catamountep.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205261	WELL	PR	03/01/2020	CBM	007-06140	PARGIN MOUNTAIN UNIT 11	PR
456218	WELL	PR	12/20/2019	CBM	007-06330	EBC 9	PR
456219	WELL	PR	12/24/2019	CBM	007-06331	EBC 10	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location

Lease Road:			
Type	Access		
comment:	Locked combo gate from Fosset Gulch road.		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Warning signs on pumpjacks.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Contents labels on chemical additives and lube oil containers.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placards on produced water tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal signs posted at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24 hour operator contact number and 911 emergency number posted on wellhead signs.

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Location has received a ground treatment to retard vegetation.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Pipe rail		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		

Comment:	2" line from Pargin Mountain wellhead to separator, 2 4" and 2 2" lines from #9 and #10 wellheads to separators, 3 lines from separators to produced water tanks, 2 2" lines from separators to #9 and #10 gas powered prime movers.			Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 3				
Comment:	Calibration date 9/25/2023.				
Corrective Action:				Date:	
Type: Other	# 1				
Comment:	Chemical additive container at the #10 separator.				
Corrective Action:				Date:	
Type: Bradenhead	# 3				
Comment:	Accessible				
Corrective Action:				Date:	
Type: Ancillary equipment	# 5				
Comment:	Telemetry, 2 electric boxes with solar panel, portable toilet, produced water transfer house.				
Corrective Action:				Date:	
Type: Bird Protectors	# 5				
Comment:	3 on separator vent stack, 2 on tank heater vent stacks.				
Corrective Action:				Date:	
Type: Prime Mover	# 3				
Comment:	Natural gas motor.				
Corrective Action:				Date:	
Type: Flow Line	# 10				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Wellhead				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 3				
Comment:					
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		37.146700,-107.382080
Comment:					

Corrective Action:					Date:	
--------------------	--	--	--	--	-------	--

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Plastic barriers with liner material.						
Corrective Action:					Date:	

Wells Served By Facilities Above

API Number	
007-06331	
007-06330	

AirsID

API Number	AirsID

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 205261 Type: WELL API Number: 007-06140 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/16/2021 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Well file reports last bradenhead test 11/16/2021, Form 17 submitted 11/24/2021.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.Date:

Facility ID: 456218 Type: WELL API Number: 007-06330 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 12/21/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 51 Fluid Type: GASEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Facility ID: 456219 Type: WELL API Number: 007-06331 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 12/21/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: GASEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Ditches	Pass	Gravel	Pass			
Gravel	Pass					
Compaction	Pass					
Berms	Pass	Ditches	Pass			
Culverts	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403556960	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280791
712700732	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280759