

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/18/2023

Document Number:

699505062**FIELD INSPECTION FORM**Loc ID 330986 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------|---------------------------------|
| , KPK | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 257527 | WELL | SI | 07/01/2023 | GW | 123-19988 | BARBARA JEAN 3-31 | SI |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Weeds unmanaged/need to be removed on location, Unused equipment needs to be removed, Stained soil by motor needs to be removed.

Corrective Action:

Comply with ruled 606

Date: 10/25/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment:

plumbed to surface

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

#

Comment:

electric

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Electric Motor

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 257527 Type: WELL API Number: 123-19988 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/19/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On 10/18/23 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Barbara Jean 3-31</p> <p>Company Name- KPK</p> <p>API- 05-123-19988</p> <p>In WeldCounty Colorado.</p> <p>While there, I observed SI well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds, Unused equipment, contaminated soil. Rule 606 10/25/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This inspection does not nullify any orders or corrective actions from the ECMC.</p> <p>At time of inspection weather conditions were warm, calm, clear.</p> <p>This is a summary of inspection report.</p> | medinaj | 10/18/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 699505063 | inspection pictures | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6289046 |