

WELL NAME: YANKOVICK #1, API #: 043-40037, INSP. # 695108710




PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: TANK BATTERY/ NO TANK BAPACITY POST ON OR AT TANK BATTERY. POST CAPACITY PER RULE 605. CA DATE 11-19-2023.





PHOTO 5: WEEDS INSIDE TANK BATTERY BERM. MAINTAIN WEEDS PER RULE 606. CA DATE 11-19-2023.





PHOTO 6: WEEDS AROUND WELLHEAD/PUMPJACK. MAINTAIN WEEDS PER RULE 606. CA DATE 11-19-2023.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 7: AREA OF IMPACTED SOIL UNDER PUMPJACK GEAR BOX. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 11-19-2023.





PHOTO 8: THERE ARE EXPOSED WIRE CONNECTIONS INSIDE WOOD ELECTRIC PANEL BOX. Securely fasten all valves, pipes, fittings, electric equipment and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 603.O(6) CA DATE 11-19-2023.






PHOTO 9: THERE ARE EXPOSED WIRE CONNECTIONS INSIDE WOOD ELECTRIC PANEL BOX. Securely fasten all valves, pipes, fittings, electric equipment and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA DATE 11-19-2023.





Colorado Oil & Gas Conservation commission
© 09-Oct-23 14:04:24

PHOTO 10: ELECTRIC PANEL IS APP. 3' FROM CRUDE OIL TANK BATTERY.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Colorado Oil & Gas Conservation commission
© 09-Oct-23 14:06:03

PHOTO 11: THERE APPEARS TO BE A RUBBER FLAP COVER ON TANK BATTERY WITH NO SAFETY VALVE INSTALLED ON TANK. Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). CA DATE 10-21-2023.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



**PHOTO 12: BRADENHEAD IS NOT ACCESSABLE. Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).
CA DATE 11-19-2023.**





PHOTO 13: TRASH INSIDE TANK BATTERY CONTAINMENT (BLUE 5 GAL. BUCKET. REMOVE TRASH PER RULE 606. CA DATE 11-19-2023.

