

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/19/2023

Document Number:

695108710

**FIELD INSPECTION FORM**Loc ID 322277 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 17210

Name of Operator: CINNAMON CREEK OIL &amp; GAS INC

Address: P O BOX 544

City: WALSH State: CO Zip: 81090

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections
Mills, Hellen		helening1221@yahoo.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210100	WELL	PR	09/01/2020	OW	043-40037	YANKOVICK 1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	PHOTO 4: TANK BATTERY/ NO TANK BAPACITY POST ON OR AT TANK BATTERY.		
Corrective Action:	POST CAPACITY PER RULE 605.	Date:	11/19/2023

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	TRASH		
Comment:	PHOTO 13: TRASH INSIDE TANK BATTERY CONTAINMENT (BLUE 5 GAL. BUCKET.		
Corrective Action:	REMOVE TRASH PER RULE 606.	Date:	11/19/2023
Type	WEEDS		
Comment:	PHOTO 5: WEEDS INSIDE TANK BATTERY BERM. PHOTO 6: WEEDS AROUND WELLHEAD/PUMPJACK.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	11/19/2023
Type	OTHER		
Comment:	PHOTO 7: AREA OF IMPACTED SOIL UNDER PUMPJACK GEAR BOX.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D	Date:	11/19/2023
Type	OTHER		
Comment:	PHOTO 8 & 9: THERE ARE EXPOSED WIRE CONNECTIONS INSIDE WOOD ELECTRIC PANEL BOX.		
Corrective Action:	Securely fasten all valves, pipes, fittings, electric equipment and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 603.O(6)	Date:	11/19/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	ADEQUATE		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	ELECTRIC DRIVE		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ELECTRIC METER AND PANELS INSIDE WOOD BOX INSIDE TANK BATTERY BERM		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PHOTO 12: BRADENHEAD IS NOT ACCESSABLE.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	11/19/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		FIBERGLASS AST		38.426278,-105.209894	
Comment:	PHOTO 11: THERE APPEARS TO BE A RUBBER FLAP COVER ON TANK BATTERY WITH NO SAFETY VALVE INSTALLED ON TANK.					
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).					Date: 10/21/2023

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 210100 Type: WELL API Number: 043-40037 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 03/21/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: [SUBMIT REPORTS](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 38.426278 Long: -105.209894Wind: Calm Speed: 0 (mph) Direction From:  Weather: Clear Temperature: 62 (F)Assisting Staff Randy Silver Camera #: ☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:41	AM	10:42	AM	

Comment: NO HYDROCARBIN EMISSIONS OBSERVED.Corrective Action:  Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695108711	FLIRR VIDEO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291538</a>
695108719	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291541">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291541</a>