

Interim Reclamation and Stormwater Inspection

Date:10/17/2023

Operator: Fundare Resources Operating Company
LLC - 10773

Location ID: 436724

Inspection Document #: 713900023

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Photo taken from the well location entrance facing North. The photo illustrates the operator sign.

Inspection Photos
Location Name: Horsetail/33M Pad
Location ID: 436724



Colorado Energy & Carbon Management Commission
Weld County
+40.7889, -103.7619
246° SW
10/17/23, 1:17 PM

Photo 2. Photo taken from the location entrance facing Northeast. The photo illustrates that the interim areas on location have been mowed.

Inspection Photos
Location Name: Horsetail/33M Pad
Location ID: 436724



Photo 3. Photo on location facing East. The photo illustrates the guy line anchors are visibly marked by yellow painted steel uprights. The photo also illustrates there has been good recruitment of vegetation in the interim but that it has been mowed.

Inspection Photos
Location Name: Horsetail/33M Pad
Location ID: 436724



Photo 4. The photo was taken from the West side of the location facing South. The photo illustrates tumbleweeds (kochia and russian thistle) up against the fence inside the location.



Photo 5. The photo was taken from the West side of the location facing North. The photo illustrates produced water inside the secondary containment.