

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/19/2023

Document Number:

712700776

FIELD INSPECTION FORMLoc ID 333997 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298141	WELL	PR	09/04/2008	CBM	067-09626	FEDERAL LAND BANK C 4	PR
298142	WELL	PR	07/13/2009	CBM	067-09627	FEDERAL LAND BANK C 3	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Long access road from CR 307, locked gate, 2C40 key.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume label, NFPA placard on produced water tank.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack, NFPA placard on separator/meter.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Sections of cattle panel and various sections of pipe and T-posts stored in separator enclosure.		
Corrective Action:	Remove unused equipment or return to service per Rule 603.f		Date: 11/20/2023
Type	OTHER		
Comment:	Observed impacted material on ground at both wellheads. See photos #3 #5.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals.		Date: 11/01/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal mesh around pumpjack weights and arms.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panel around wellhead and pumpjack.		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panel around produced water tank, unitized separator/meter, telemetry, and electrical service box.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 2		
Comment:	Electrical control boxes.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Unitized separator and metering. Calibration date 7/26/2023.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry, electric service box.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	2-3" line from wellhead to separator.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.151100,-107.775830
Comment:	Partially buried steel tank, labeled 95 bbl.				
Corrective Action:				Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-08261		
067-09626		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298141 Type: WELL API Number: 067-09626 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/25/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 298142 Type: WELL API Number: 067-09627 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/25/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Culverts	Pass			
Waddles	Pass	Gravel	Pass			
Compaction	Pass					
Ditches	Pass	Ditches	Pass			

Comment: No visible erosion or sediment migration observed during inspection.Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700778	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291709