

WELL NAME: HILL RANCH 29-15, API #: 071-06458, INSP. # 695108684



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION





PHOTO 3: V WELLHEAD AND EQUIPMENT



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 4: R WELLHEAD AND EQUIPMENT





PHOTO 5: AREA OF IMPACTED SOIL APPEARS TO BE FROM A PREVIOUS HYDRAULIC HOSE LEAK (NO LEAK AT TIME OF INSPECTION). Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 11-19-2023.

