




99999999

OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORTJUL 12 1996  
C

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <del>017</del> <sup>017</sup> <del>7413</del> <sup>6021</sup>		LEASE NAME: <u>MILLER</u> <del>REDA</del> #1	
LOCATION: <u>SENE12-155-45W</u>		OPERATOR: <u>GILBERT STEWART</u> <sup>Murfin</sup>	
DATE: <u>6-19-96</u>		INSPECTOR: <u>R. VanSickle</u>	
Insp. Type: <u>SR</u>	Insp. Status: <u>PA</u>	PA: Y <u>N</u>	Pass/Fail: P <u>F</u> Viol.: <u>Y</u> N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	<i>Timbers @ site, Submersible pump control box.</i>	
Miscellaneous		

*This is  
Murfin's cleanup.*



CORRECTIVE ACTION REQUIRED: *Remove timbers, fill in hole, Remove control box.*

Date Corrective Action Required By: 8-19-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00553971