

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/19/2023

Document Number:

708901987

FIELD INSPECTION FORMLoc ID 335810 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

29 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272507	WELL	PR	09/01/2021	GW	045-10089	FEDERAL RWF 22-18	PR
272529	WELL	PR	02/01/2012	GW	045-10093	FEDERAL RWF 322-18	PR
272530	WELL	PR	02/09/2005	GW	045-10092	FEDERAL RWF 332-18	PR
272531	WELL	PR	09/01/2021	GW	045-10091	FEDERAL RWF 32-18	PR
277377	WELL	PR	04/01/2012	GW	045-10691	FEDERAL RWF 531-18	PR
277378	WELL	PR	02/08/2006	GW	045-10692	FEDERAL RWF 431-18	PR
277379	WELL	PR	12/08/2005	GW	045-10693	FEDERAL RWF 331-18	PR
277380	WELL	PR	05/01/2007	GW	045-10694	FEDERAL RWF 31-18	PR

General Comment:**CECMC Inspection Report Summary**

On 10/18/2023 at approximately 11:36 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 pad.

Location # 335810 in Garfield County Colorado.

Please refer to inspection 707800076 conducted on 12/21/2022, previous corrective action has been completed.

Location is within close proximity to High Priority/Density Habitat areas.

Location is approximately 14 yards from a creek/drainage that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign weathered & cracking but legible		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label has incorrect capacity		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead signs weathered & cracking but legible		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels - panels around wellheads are starting to fall down		

Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	RWF 31-18 & RWF 22-18 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible. Remaining 6 wells have no form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Inspector Name: Smelser, Wayne

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	272507	Type:	WELL	API Number:	045-10089	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	272529	Type:	WELL	API Number:	045-10093	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	272530	Type:	WELL	API Number:	045-10092	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	272531	Type:	WELL	API Number:	045-10091	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	277377	Type:	WELL	API Number:	045-10691	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	277378	Type:	WELL	API Number:	045-10692	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	277379	Type:	WELL	API Number:	045-10693	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	277380	Type:	WELL	API Number:	045-10694	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Gravel				Sparse in sections
				Material Handling And Spill Prevention		Chemical tank containment
Ditches						
Compaction						Light compaction in multiple areas
		Ditches				
Gravel						Sparse to none in areas
		Culverts				
Rip Rap						
		Compaction				
Check Dams						
Retention Ponds						
Berms						

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901988	Inspection 708901987 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291876
708901989	Inspection 708901987 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291877