

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #1 Well sign.



Photo #2 Crude tanks.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #3 Meters.



Photo #4 Separator house.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #5 weeds in vault berm.



Photo #6 P/W vault.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #7 P/W vault.



Photo #8 Open pit.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #9 Hydrocarbons in the bottom of open pit.



Photo #10 Pump jack.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #11 Well head.



Photo #12 Stained soil around well head.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #13 stained soil in berm around crude tanks.



Photo #14 Stained soil under Crude tank.

Inspection Photos
Location Name: CHAMPLIN_HER_2-8
Location ID: 320245



Photo #15 Meter for well site



Video #1 of well active venting.