

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2023

Submitted Date:

10/20/2023

Document Number:

708901996

FIELD INSPECTION FORM

Loc ID 335135 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211244	WELL	PR	12/09/1995	GW	045-07003	FEDERAL RMV 58-20	PR
279140	WELL	PR	03/12/2006	GW	045-11002	GARFIELD COUNTY RWF 431-20	PR
279141	WELL	PR	04/10/2006	GW	045-11003	GARFIELD COUNTY RWF 531-20	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 10/20/2023 at approximately 11:49 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 58-20 Pad. Location # 335135 in Garfield County Colorado. Please refer to inspection 708901582 conducted on 09/07/2023, previous corrective action has been completed. Location is within High Priority/Density Habitat areas. Location is approximately 214 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/Split pad - wellheads only: tank battery & production separators located on the CLOUGH RMV 55-20 pad, location # 335251

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Small amount of debris on location		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Equipment:			
Type: Bradenhead	# 3		corrective date
Comment:	RMV 58-20 well has Taylor plug located on bradenhead, bradenhead valve is accessible. Remaining 2 wells have no form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4	
Comment:	Marked	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>211244</u>	Type: <u>WELL</u>	API Number: <u>045-07003</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>279140</u>	Type: <u>WELL</u>	API Number: <u>045-11002</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>279141</u>	Type: <u>WELL</u>	API Number: <u>045-11003</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
Compaction						Light compaction in some areas
		Gravel				
Culverts						
Check Dams						
Ditches						
Gravel						Sparse in some areas
Berms						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
This location is within the Garfield County Landfill.	smelserw	10/20/2023
Remote location/Split pad - wellheads only: tank battery & production separators located on the CLOUGH RMV 55-20 pad, location # 335251		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901997	Inspection 708901996 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6292794
708901998	Inspection 708901996 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6292795