

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SESW

Location ID: 335183

Date: 10/17/2023



Location Entrance – Photo #07012



Wellheads – Photo #07018

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SESW

Location ID: 335183

Date: 10/17/2023



Separators – Photo #07013



Tank Battery – Photo #07015

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SESW

Location ID: 335183

Date: 10/17/2023



Location Lacks Stabilization – Photo #07014



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07019