




Photograph 1: Stormwater outside secondary containment area. Staining in foreground. East corner of the facility facing southeast.



Photograph 2: Stormwater inside and outside secondary containment area. East corner of the facility facing southeast.





Photograph 3: Stormwater inside and outside secondary containment area. East corner of the facility facing east. Staining present on sides of secondary berm.



Photograph 4: Dry area inside secondary containment. Staining along evaporation line. East corner of the facility facing south.





Photograph 5: Close up of staining inside secondary containment. No visible sheen on stormwater at time of discovery. East corner of the facility facing east.



Photograph 6: Tanks within secondary containment. East corner of the facility facing east.





Photograph 7: Close up of piping at tank base. No staining or evidence of leakage from piping.



Photograph 8: South end of secondary containment. No staining or evidence of impacts from excess stormwater. East corner of facility, facing southwest.