

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Location Overview: Location is within High Priority/Density Habitat areas. Location is approximately 138 yards from a creek/drainage that contributes to the Colorado River.

Section/Township/Range: 20 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3440 Erosion & transport of sediment on lease road /insufficient BMP's



Photo # 3441 Erosion & transport of sediment on lease road /insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3442 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3443 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3444 Erosion & transport of sediment on lease road /insufficient BMP's



Photo # 3445 Erosion & transport of sediment on lease road /insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



**Photo # 3446 Erosion & transport of sediment on lease road
/insufficient BMP's**



**Photo # 3447 Erosion & transport of sediment on lease road
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3448 Erosion & transport of sediment on lease road /insufficient BMP's



Photo # 3449 Erosion & transport of sediment on lease road /insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



**Photo # 3450 Erosion & transport of sediment on lease road
/insufficient BMP's**



**Photo # 3451 Erosion & transport of sediment on lease road
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3452 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3453 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3454 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3455 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3456 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3457 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3458 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3459 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3460 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3461 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3462 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3463 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3464 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3465 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3466 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3467 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3468 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3469 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3470 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3471 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Oct 20, 2023 at 9:57:10 AM
CO

Photo # 3472 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Oct 20, 2023 at 9:57:31 AM
CO

Photo # 3473 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad
Location ID: 335263



Photo # 3474 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's



Photo # 3475 Erosion & transport of sediment off lease road into a vegetated area choking off vegetation/insufficient BMP's