

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/23/2023

Document Number:

701007529**FIELD INSPECTION FORM**Loc ID 321045 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crane, Shaun	719-353-2526	cimbaca.production.services@gmail.com	
Kelly, George	(888) 858-7886	envexbaca@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205853	WELL	PR	05/01/2020	GW	009-06268	ROBBINS RANCH 'C' 1	PR

**General Comment:**Routine Inspection

## Location

<b>Lease Road:</b>			
Type	Other		
comment:	Access wellhead through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sticker and stencil on tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/19/2023
Type	BATTERY		
Comment:	Lease sign by tank. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	11/19/2023

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds across location need maintenance		
Corrective Action:	Comply with Rule 606	Date:	11/19/2023

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Oilwell unit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed is 1450' SSW of wellhead on SE side of CR X & 51		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		37.298440,-102.149990	
Comment:	Water tank is 500' west of wellhead. Tank is empty, disconnected and not in use at time of inspection					
Corrective Action:	Remove water tank from location or install berms for containment				Date:	11/19/2023

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 205853 Type: WELL API Number: 009-06268 Status: PR Insp. Status: PR**Producing Well**Comment: Meter run is 1450' SSW of wellhead on south side of CR X & 51. Wellhead is SI at time of inspectionCorrective Action: Submit production reports for previous 6 monthsDate: 11/19/2023**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well is TA at time of inspection and incapable of productionCorrective Action: Submit Sundry notice for current status of wellDate: 11/19/2023

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007536	Tank photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294008</a>
701007537	Wellhead photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294009">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294009</a>