

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



Photo # 3803 From entrance to location



Photo # 3804 Location

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad**  
**Location #: 324017**



**Photo # 3805 Location**



**Photo # 3806 Location**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



Photo # 3807 Location



Photo # 3808 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



**Photo # 3809 Flowline heating insulation open ended**



**Photo # 3810 Flowline heating insulation open ended**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



**Photo # 3811 Fence is in disrepair & needs maintenance**