

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2023

Submitted Date:

10/23/2023

Document Number:

708902024**FIELD INSPECTION FORM**Loc ID 324017 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211498	WELL	PR	06/01/2021	GW	045-07258	CLEM 15-14	PR

General Comment:**CECMC Inspection Report Summary**

On 10/23/2023 at approximately 13:10 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad.
Location # 324017 in Garfield County Colorado.
Location is within High Priority/Black Bear/Density Habitat areas.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Flowline heating insulation open ended with a CA date of 10/30/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-2615			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Barbed wire fence Fence is in disrepair & needs maintenance			
Corrective Action:				Date:
Equipment:				
Type: Horizontal Heated Separator	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			

Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Flowline heating insulation open ended		
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.	Date:	10/30/2023
Type: Bradenhead	# 1		
Comment:	Pressure transducer located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211498	Type:	WELL	API Number:	045-07258	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse in sections
Gravel						Sparse in areas
		Ditches				
Compaction						Light compaction in some areas
		Waddles				
		Compaction				Light compaction in some sections
		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	10/23/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902025	Inspection 708902024 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6295241
708902026	Inspection 708902024 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6295242