

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



**Location Overview: Location is within High Priority/Black Bear/Density Habitat areas & in close proximity to NSO Habitat area. Location is approximately 384 yards from Battlement Creek. Location is within close proximity to Rule 411a Surface Water External Buffer.
Section/Township/Range: 15 7S95W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3845 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3846 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3847 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3848 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3849 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3850 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3851 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3852 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3853 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3854 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3855 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3856 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3857 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3858 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3859 Lack of stabilization/compaction/insufficient tracking BMP's

Photo # 3860 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad
Location #: 324264



Photo # 3861 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3862 Lack of stabilization/compaction/insufficient tracking BMP's