

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	produced water tank volume faded, Sign not posted or information inaccurate at oil and gas location		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	11/24/2023
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	chain link panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation panels		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	calibration 8-2023		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:	produced water tank volume faded, Sign not posted or information inaccurate at oil and gas location				
Corrective Action:	Install sign to comply with Rule 605.a.				Date: 11/24/2023

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shared with condensate tank			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 206748 Type: WELL API Number: 013-06243 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/08/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: submit report

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 10-24-2023 at approximately 13:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Zwick F unit 1 Operator: Crestone Peak Resources API#: 013-06243 County: Boulder While there, I observed producing well site and production site. During this inspection the following possible compliance issues were observed: Battery sign, Rule 605a, corrective action date 11-24-2023, photo 3 Weather conditions: dry and sunny A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	10/24/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300235	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6296948