



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	cut vegetation left on location		
Corrective Action:	comply with Rule 606	Date:	11/01/2023
Type	UNUSED EQUIPMENT		
Comment:	unused pump jack and concrete pad has been unused on location since 2019, and unused steel fencing where the transformers and electric panel once set.		
Corrective Action:	comply with rule 606	Date:	11/24/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Pump Jack	# 1		
Comment:	unused		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239878 Type: WELL API Number: 123-07666 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/07/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Tuesday 10-24-2023 at approximately 1315 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: KP Kauffman                      Location name: John A. Kunzman 62N66W 5SESW                      Well name: John A. Kunzman #1                      API #05-123-07666                      County: Weld                      Weather: Clear, cloudy.                      Location: Dry.                      While there, I observed a wellsite, SI at the time of the inspection.                      During this inspection, I observed the following possible compliance issues:                      606 housekeeping: CA date 11-24-2023                      See attached photos.                      A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	10/24/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402425	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6297028">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6297028</a>