

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2023

Submitted Date:

10/25/2023

Document Number:

708902040

FIELD INSPECTION FORMLoc ID 323781 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456927	Domestic Tap	AC	08/28/2018		-	Domestic Tap 11NWNW	AC

General Comment:**CECMC Inspection Report Summary**

On 10/24/2023 at approximately 12:40 hours, I, Compliance Specialist, Wayne Smelser
Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap11NWNW
Location # 323781 in Garfield County Colorado.
While there, I observed the domestic tap is derived from FORSTER W-46-11 well casing valve.

This is a summary of inspection report

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment: [911/970-285-9377](#)

Corrective Action: Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pipe rail fence & hog panels around domestic tap		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Domestic tap		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	456927	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	While there, I observed the domestic tap is derived from FORSTER W-46-11 well casing valve. The pressure is regulated by a regulator. Following the regulator there is another regulator & then a small fluid knock out, after that there is an in line odorizer & a PRV. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Domestic tap inspection only	smelserw	10/25/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902041	Inspection 708902040 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6297512