

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/13/2023

Submitted Date:

10/25/2023

Document Number:

697602206

FIELD INSPECTION FORMLoc ID 336574 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245201	WELL	SI	08/01/2020	GW	123-12996	KEENAN-UPRR 41-15	EI
288946	WELL	AL	10/30/2007	LO	123-24691	MORNING 41-15	EI
294418	WELL	SI	08/01/2020	GW	123-25350	MORNING 41-15	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: All signage is adequate.

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Fencing around the excavation and wellheads are adequate.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>245201</u>	Type:	<u>WELL</u>	API Number:	<u>123-12996</u>	Status:	<u>SI</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>288946</u>	Type:	<u>WELL</u>	API Number:	<u>123-24691</u>	Status:	<u>AL</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>294418</u>	Type:	<u>WELL</u>	API Number:	<u>123-25350</u>	Status:	<u>SI</u>	Insp. Status:	<u>EI</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	Stockpiled soil on location from the excavation.			
Corrective Action	Properly treat or dispose of E&P waste in accordance with Rule 905.			Date: 10/27/2023

Spill/Remediation:

Comment:	Open excavation for spill remediation. Operator is active with the remediation.			
Corrective Action:				Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403573000	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6298319
697602207	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6298307