

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2023

Submitted Date:

10/19/2023

Document Number:

697602189

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Anderson, Laurel		laurel.anderson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482278	SPILL OR RELEASE	CL	03/14/2023		-	Sack 8-11	EI

General Comment:

[This is an Environmental inspection to document remediation activities at Sack 8-11 Facility ID #482278. Operator personnel were on location during the time of the inspection. Any corrective actions/conditions of approval from previous inspections/forms that have not been addressed remain applicable. Photos are attached to document site conditions at the time of the inspections.](#)

[Operator personnel were on location backfilling the excavation with off-site soil.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Weeds were overgrown throughout the site location.

Corrective Action: Comply with Rule 606.

Date: 10/26/2023

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment: Orange fencing around the excavation was mostly taken down in order to backfill the excavation.

Corrective Action:

Date:

Equipment:

corrective date

Type:	#

Comment: No equipment on site

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 482278 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Comment	Clean soil was brought in for excavation backfill.			
Corrective Action				Date:

Spill/Remediation:

Comment:	The spill excavation was being backfilled at the time of the inspection.		
Corrective Action:		Date:	_____

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403566199	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291161
697602190	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291159