

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/19/2023

Document Number:

707601971

**FIELD INSPECTION FORM**

Loc ID 323370	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
------------------	--------------------------------	---	-------------------	--

**Operator Information:**  
 OGCC Operator Number: 100322  
 Name of Operator: NOBLE ENERGY INC  
 Address: 2001 16TH STREET SUITE 900  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323370	LOCATION	AC			-	HOLMAN-65N64W 14SWNE	IO

**General Comment:**  

This is a BATTERY inspection.  
 Well(s): 1: Temporarily Abandoned | TA.  
 Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (323370).  
 (Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:  
 A.) Field Inspection Report doc. #707601969 and/or Location ID #323370 for TA Well(s) info.  
 B.) Field Inspection Report doc. #707601971 and/or Location ID #323370 for Battery / Facility, Equipment info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Overgrown vegetation at produced H2O vault. Refer to Rule 606.c for guidance. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.			
Corrective Action:	*Remove, manage, & control overgrown vegetation around produced H2O vault. Comply with Rule 606.c. Corrective Action date: 11/20/2023. (30-days). See photo #3.			Date: <u>11/20/2023</u>
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Surrounded by earth berms.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
Comment:	Gas Sales: Calibration card(s) indicates calibration > 1 year. Last calibration: 07/22/2014. Inactive, NO production.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	<a href="#">Centralized Battery serves 1 Location ID (323370).</a> <a href="#">(Well(s): 1: Temporarily Abandoned   TA).</a> <a href="#">Centralized Battery serves 1 Tank Battery Facility ID (Pending).</a>				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.399380,-104.514370
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	<a href="#">Berms shared w/ crude oil tank(s), South produced H2O vault(s).</a>				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	CONCRETE SUMP/VAULT		40.401416,-104.513819
Comment:					
Corrective Action:					
Date:					

Paint

Condition		
Other (Content)		
Other (Capacity)	60 Bbls.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	24 Bbls.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Berms shared w/ crude oil tank(s), South produced H2O vault(s).			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On THU 10/19/2023 at approximately 11:47 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: NOBLE ENERGY INC  Facility Name: Pending  Facility ID: Pending  Location Name: SLW RANCH B/01-66-1HN  Location ID: 430823  Well Name(s):  Holman 14-1.  API:  123-12922.  Location County: Weld County, Colorado  Weather: Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Location ID (323370).  (Well(s): 1: Temporarily Abandoned   TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference:  A.) Field Inspection Report doc. #707601969 and/or Location ID #323370 for TA Well(s) info.  B.) Field Inspection Report doc. #707601971 and/or Location ID #323370 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issue(s) were observed:  1.) Overgrown vegetation at produced H2O vault.  Refer to Rule 606.c for guidance.  *Remove, manage, &amp; control overgrown vegetation around produced H2O vault.  Comply with Rule 606.c.  Corrective Action date: 11/20/2023. (30-days).  See photo #3.  *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/19/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403566549	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291473</a>
707601972	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291469</a>