

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/19/2023

Document Number:

712700773**FIELD INSPECTION FORM**Loc ID 325674 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|--------------------|
| , General | | sjninspections@ikavenergy.com | All SW Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 215213 | WELL | PR | 02/01/2020 | CBM | 067-06818 | FEDERAL LAND BANK C 1 | PR |

General Comment:SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.
Equipment inventory listed on previous inspection, no change to location equipment.

New corrective action identified, see Housekeeping section.

Location**Lease Road:**

| | | | |
|-------------------|-----------------------|-------|--|
| Type | Access | | |
| comment: | Locked gate, 2C40 key | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|---|-------|--|
| Type | WELLHEAD | | |
| Comment: | Metal sign posted at location entrance. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Contents and volume label, NFPA placard on produced water tank. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | NFPA placard on separator. Warning signs on pumpjack. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|---|-------|--|
| Comment: | 24 hour operator contact number and 911 local emergency number posted on well location signage. | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | OTHER | | |
| Comment: | Observed impacted material on ground at muffler outlet. See photo #3. | | |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals. | Date: | 11/01/2023 |

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-------------------------|----------------------------|------------------------|-------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 215213 | Type: | WELL | API Number: | 067-06818 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 05/25/2023 | Annual Brhd Completed? | Yes | | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 0 | Fluid Type: | | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Berms | Pass | Culverts | Pass | Material Handling And Spill Prevention | Pass | Container within containment. |
| Gravel | Pass | | | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Rip Rap | Pass | Ditches | Pass | | | |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403566729 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291718 |
| 712700777 | INSPECTION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291708 |