

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



**Location Overview: Location is within High
Priority/NSO/Black Bear/Density Habitat areas. Location is
approximately 129 yards from West Mamm Creek.
Section/Township/Range: 13 7S93W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4275 Berm around stockpiled soils has eroded/BMP needs maintenance



Photo # 4276 Berm around stockpiled soils has eroded/BMP needs maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4277 Vehicle tracks through berm around stockpiled soils/BMP needs maintenance



Photo # 4278 Vehicle tracks through berm around stockpiled soils/BMP needs maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4279 Berm around stockpiled soils has partially eroded/BMP needs maintenance



Photo # 4280 Berm around stockpiled soils has partially eroded/BMP needs maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4281 Berm around stockpiled soils has partially eroded/BMP needs maintenance



Photo # 4282 Vehicle tracks through berm around stockpiled soils/BMP needs maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4283 Vehicle tracks through berm around stockpiled soils/BMP needs maintenance



Photo # 4284 Lack of stabilization/compaction on location soils/BMP

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4285 Lack of stabilization/compaction on location



Photo # 4286 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4287 Lack of stabilization/compaction on location



Photo # 4288 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4289 Lack of stabilization/compaction on location



Photo # 4290 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4291 Lack of stabilization/compaction on location



Photo # 4292 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4293 Lack of stabilization/compaction on location



Photo # 4294 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4295 Lack of stabilization/compaction on location



Photo # 4296 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4297 Lack of stabilization/compaction on location



Photo # 4298 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4299 Lack of stabilization/compaction on location



Photo # 4300 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4301 Lack of stabilization/compaction on location



Photo # 4302 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4303 Lack of stabilization/compaction on location



Photo # 4304 Lack of stabilization/compaction near entrance to location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4305 Lack of stabilization/compaction near entrance to location



Photo # 4306 Lack of stabilization/compaction near entrance to location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4307 Lack of stabilization/compaction at entrance to location



Photo # 4308 Lack of stabilization/compaction at entrance to location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4309 Lack of stabilization/compaction on lease road near entrance to location



Photo # 4310 Lack of stabilization/compaction on lease road near entrance to location