

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2023

Submitted Date:

10/26/2023

Document Number:

712700785

FIELD INSPECTION FORMLoc ID 313551 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10810

Name of Operator: MESSER LLC

Address: 200 SOMERSET CORP BLVD #7000

City: BRIDGEWATER State: NJ Zip: 08807

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

29 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hom, Brian	(908) 771-1625	Brian.hom@messer-us.com	All SW Inspections
DeMarco, Jaime		jdemarco@blm.gov	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Pienta, Brad	(908) 952-4528	Brad.pienta@messer-us.com	All SW Inspections
Hartman, Laura		lhartman@blm.gov	All SW Inspections
Engineering, General		dnr_ecmc_engineering@state.co.us	Engineering
Twitty, Melita	(908) 771-1894	Melita.twitty@messer-us.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112976	PIT	AC	09/23/1999		-	AIRCO DUDLEY 5	AC
224457	WELL	PR	11/30/2007	CO2	083-06522	AIRCO DUDLEY 5	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Access from CR G. Long access across private land. Locked gate at BLM boundary, BLM combo lock. Road is four-wheel drive only, rough, exposed bedrock road surface in areas.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Warning signs on separator shed.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number is functional, well location signage missing local or 911 emergency services number. No posted information addressing public road access to well location.		
Corrective Action:	Post local emergency services number or 911 on well location signage. Post public road used to access the well on signage.		Date: 11/25/2023
Good Housekeeping:			
Type	WEEDS		
Comment:	Undesirable vegetation growing on pit containment berms. Grass growing around wellhead.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail enclosure at wellhead.		
Corrective Action:			Date:
Type	PIT		
Comment:	Corrugated metal enclosure around pit containment berm.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	4" line from separator to digital meter. Meter calibration record unavailable.		

Corrective Action:		Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).	Date:	11/10/2023
Type: Ancillary equipment	# 2			
Comment:		Solar panels.		
Corrective Action:			Date:	
Type: Other	#			
Comment:		Self contained spill response kit.		
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:		Wellhead		
Corrective Action:			Date:	
Type: Bradenhead	# 0			
Comment:		No access		
Corrective Action:		Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	11/10/2023
Type: Flow Line	# 1			
Comment:		2" line from wellhead to separator.		
Corrective Action:			Date:	
Type: Other	# 1			
Comment:		150 gallon propane tank.		
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:		COGCC does not have a Form 44 registration on record for surface lines. This was recorded as a corrective action on a previous inspection in 2021, with a different operator.		
Corrective Action:			Date:	
Type: Deadman # & Marked	# 2			
Comment:		One unmarked guy anchor.		
Corrective Action:		Adequately mark guy anchor per Rule 1003.	Date:	11/09/2023
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 112976 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 224457 Type: WELL API Number: 083-06522 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: No Form 17 in well file.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel						
Ditches	Pass	Ditches	Pass	Spill Response	Pass	Self contained spill response kit.

Comment: Observed sediment migration onto location from south side cut slopes.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 112976Lat: 37.373350Long: -108.788000Reference Point: SE

Other: _____

Length: _____

Width: _____

Lining:Liner Type: OtherLiner Condition: AdequateComment: Synthetic material

Corrective Action

Date: _____

Fencing:Fencing Type: OtherFencing Condition: AdequateComment: Corrugated metal, steel posts.

Corrective Action

Date: _____

Netting:Netting Type: MeshNetting Condition: GoodComment: Steel column supports, wire rope suspension of netting.

Corrective Action

Date: _____

Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700787	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299824