

Inspection Photos
Operator: SCOUT ENERGY MANAGEMENT LLC - 10779
Location Name: EMERALD #98X
Location ID: 428384 API #: 05-103-11915
Inspection Date: 10/26/2023 Inspection Doc#: 693806504



Injection well during MIT

Click here to read the form
Oil and Gas Conservation Commission
MECHANICAL INTEGRITY TEST

Well Information:
 Well Name: **Weber**
 Well ID: **6725-6829**
 Well Type: **Injection Well**
 Well Status: **Active**
 Well Depth: **6724.7**
 Well Diameter: **6037.2**
 Well Completion: **10/26/23**
 Well Completion Date: **10/26/23**
 Well Completion Time: **13:10**
 Well Completion Location: **10/26/23**
 Well Completion Operator: **10/26/23**
 Well Completion Signature: **10/26/23**

Test Results:
 Test Type: **Pressure Test**
 Test Results: **Pass**
 Test Results Description: **Pressure Test Results**
 Test Results Signature: **10/26/23**
 Test Results Date: **10/26/23**
 Test Results Time: **13:10**
 Test Results Location: **10/26/23**
 Test Results Operator: **10/26/23**
 Test Results Signature: **10/26/23**

Signatures:
 Operator Signature: **10/26/23**
 Inspector Signature: **10/26/23**
 Date: **10/26/23**
 Time: **13:10**
 Location: **10/26/23**
 Operator: **10/26/23**
 Inspector: **10/26/23**

Form 21 field copy