

Inspection Photos

Loc: 309022

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/26/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. This culvert along the main access road is filled in with sediment at Lat/Long:37.302109, -104.78223 .



Inspection Photos



Photo 2. There is erosion along the roadside near the Rampart 43-33 well site.



Inspection Photos



Photo 3. Facing southwest along the switch back of the access road which has erosion issues.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309022 | Date: 10/26/2023

Inspection Photos



Photo 4. Facing southeast along the access road. There is erosion occurring down the center of the road.



Inspection Photos



Photo 5. Facing southeast along the access road. The culvert at the red arrow is filled in with sediment and which is causing stormwater to flow down the road.



Inspection Photos



Photo 6. Facing toward the location.

