

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/23/2023

Document Number:

701007529

FIELD INSPECTION FORMLoc ID 321045 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kelly, George	(888) 858-7886	envexbaca@aol.com	
Crane, Shaun	719-353-2526	cimbaca.production.services@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205853	WELL	PR	05/01/2020	GW	009-06268	ROBBINS RANCH 'C' 1	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Other		
comment:	Access wellhead through farm ground		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 11/19/2023
Type	TANK LABELS/PLACARDS		
Comment:	Sticker and stencil on tank		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign by tank. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 11/19/2023
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds across location need maintenance		
Corrective Action:	Comply with Rule 606		Date: 11/19/2023
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Meter shed is 1450' SSW of wellhead on SE side of CR X & 51		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Oilwell unit		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		37.298440,-102.149990	
Comment:	Water tank is 500' west of wellhead. Tank is empty, disconnected and not in use at time of inspection					
Corrective Action:	Remove water tank from location or install berms for containment				Date:	11/19/2023

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 205853 Type: WELL API Number: 009-06268 Status: PR Insp. Status: PR**Producing Well**Comment: Meter run is 1450' SSW of wellhead on south side of CR X & 51. Wellhead is SI at time of inspectionCorrective Action: Submit production reports for previous 6 monthsDate: 11/19/2023**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Well is TA at time of inspection and incapable of productionCorrective Action: Submit Sundry notice for current status of wellDate: 11/19/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403568536	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294012
701007536	Tank photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294008
701007537	Wellhead photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6294009