

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2023

Submitted Date:

10/27/2023

Document Number:

707601989**FIELD INSPECTION FORM**Loc ID 322785 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
322785	LOCATION	AC			-	WHITE-65N64W 34NWNW	IO

General Comment:

This is a BATTERY inspection.

Well(s): 2: Shut-In | SI ; 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs

(322785, 305926, 319624).

(Well(s): 2: Shut-In | SI ; 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 3 Location ID

(305134, 322774, 327063).

(Well(s): 3: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(Pending).

Reference:

A.) Field Inspection Report doc. #707601979 and/or Location ID #322785 for SI Well(s) info.

B.) Field Inspection Report doc. #707601981 and/or Location ID #305926 for TA Well(s) info.

C.) Field Inspection Report doc. #707601983 and/or Location ID #319624 for SI Well(s) info.

D.) Field Inspection Report doc. #707601985 and/or Location ID #305134 for PA Well(s) info.

E.) Field Inspection Report doc. #707601987 and/or Location ID #322774 for PA Well(s) info.

F.) Field Inspection Report doc. #707601989 and/or Location ID #322785 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	Battery site: Propane. Placards.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Battery site: 1: Propane tank. 1: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF Shut-down.		

Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas Sales: Calibration card(s): NOT Posted. Inactive, NO production.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 3 Location IDs (322785, 305926, 319624). (Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.362834,-104.542734
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Berms shared w/ crude oil, produced H2O tank(s).					
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 10/25/2023 at approximately 16:07 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: WHITE-65N64W/34NWNW Location ID: 322785 Well Name(s): White 34-2, White 34-1, White 1-1. API: 123-12050, 123-11585, 123-23689. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (322785, 305926, 319624). (Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 3 Location ID (305134, 322774, 327063). (Well(s): 3: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707601979 and/or Location ID #322785 for SI Well(s) info. B.) Field Inspection Report doc. #707601981 and/or Location ID #305926 for TA Well(s) info. C.) Field Inspection Report doc. #707601983 and/or Location ID #319624 for SI Well(s) info. D.) Field Inspection Report doc. #707601985 and/or Location ID #305134 for PA Well(s) info. E.) Field Inspection Report doc. #707601987 and/or Location ID #322774 for PA Well(s) info. F.) Field Inspection Report doc. #707601989 and/or Location ID #322785 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/27/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403574925	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300283
707601990	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300277