

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/12/2023

Submitted Date:

10/13/2023

Document Number:

712700738

**FIELD INSPECTION FORM**

Loc ID 333611 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10734  
Name of Operator: HIGH RIVER RESOURCES OPERATING LLC  
Address: 3838 OAK LAWN AVE SUITE 710  
City: DALLAS State: TX Zip: 75219

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 20 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@highriverllc.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Vaughn, Robert		rvaughn@highriverllc.co	<a href="#">Primary Contact</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213922	WELL	PR	02/01/2019	GW	067-05192	SCHOFIELD AUTO 41-6	PR

**General Comment:**

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access from CR 319.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location warning signs.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placard on produced water tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at wellhead fencing.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	24 hour operator contact number is posted, no 911 emergency number posted on well location signage.		
Corrective Action:	Post local emergency services number or 911 on well location signage.		Date: 11/12/2023
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Two Red Willow Production wells share the location.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panel enclosure at wellhead.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to meterhouse. Calibration date 5/11/2023.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	One unmarked guy anchor.		
Corrective Action:	Mark or remove anchors as unused equipment if non-serviceable or no longer needed for ongoing oil and gas operations.	Date:	10/27/2023
Type: Flow Line	# 1		
Comment:	2" line from wellhead to separator.		
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	Buried valve can.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		37.050380,-107.645980
Comment:	Screened, open top steel tank, signed 125 bbl.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Observed daylight under metal containment ring. Containment not impervious. See Photo #6.				
Corrective Action:	Comply with the OLD Rules 605.a(4) and 906.d(1).			Date:	11/13/2023

**Venting:**

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 213922 Type: WELL API Number: 067-05192 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/10/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass			
Compaction	Fail	Ditches	Pass			

Comment: [Observed erosional channel and sediment migration off site. See Photo #5.](#)

Corrective Action: [Install or repair required BMPs.](#)

Date: 10/27/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403560225	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6283859">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6283859</a>
712700746	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6283844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6283844</a>